



GREG BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection: OGM Karl Houskeeper

Inspection Report

Permit Number:	C0070042
Inspection Type:	COMPLETE
Inspection Date:	Thursday, September 16, 2010
Start Date/Time:	9/16/2010 11:30:00 AM
End Date/Time:	9/16/2010 3:30:00 PM
Last Inspection:	Tuesday, August 31, 2010

Inspector: Karl Houskeeper,
Weather: Clear, Temp. 72 Deg. F.
InspectionID Report Number: 2499

Accepted by: jhelfric 9/20/2010

Permitee: SUNNYSIDE COGENERATION ASSOCIATES
Operator: SUNNYSIDE COGENERATION ASSOCIATES

Site: STAR POINT REFUSE

Address: PO BOX 159, SUNNYSIDE UT 84539

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Cur	ren	tΔ	cre	an	٥٥
-ui	1011			αч	5 3

152.93	Total Permitted		
152.93	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Mineral Ownership

Types of Operations

Underground

☐ Federal ☐ Underground
☐ State ☐ Surface
☐ County ☐ Loadout
✔ Fee ☐ Processing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Richard Safley SCA was present during the inspection.

Inspector's Signature:

Kel R. Nousbuper

Date

Thursday, September

embe**/16,** 2010

Karl Houskeeper,

Inspector ID Number: 49

Permit Number: C0070042 Inspection Type: COMPLETE

Inspection Date: Thursday, September 16, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓			
4.e	Hydrologic Balance: Effluent Limitations	✓		✓	
5.	Explosives	V	✓		
6.	Disposal of Excess Spoil, Fills, Benches	✓			
7.	Coal Mine Waste, Refuse Piles, Impoundments	V		✓	
8.	Noncoal Waste	V			
9.	Protection of Fish, Wildlife and Related Environmental Issues	V			
10.	Slides and Other Damage	✓			
11.	Contemporaneous Reclamation	✓			
12.	Backfilling And Grading	V			
13.	Revegetation	V			
14.	Subsidence Control	✓			
15.	Cessation of Operations	~			
16.a	Roads: Construction, Maintenance, Surfacing	✓			
16.b	Roads: Drainage Controls	✓			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	~			
19.	AVS Check	V			
20.	Air Quality Permit	✓		✓	
21.	Bonding and Insurance	✓		✓	
22.	Other	✓			

Permit Number: C0070042 Inspection Type: COMPLETE

Inspection Date: Thursday, September 16, 2010

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The following permits were reviewed:

- -Mining permit C/007/042 issued November 14, 2008 and expires November 14, 2013.
- -UPDES permit #UTG040025 effective May 1, 2008 and expires midnight April 30, 2013 (under general permit UTG040000).
- -Air Quality Permit DAQE-239-02 issued April 1, 2002, remains in effect.
- -SPCC plan is not required.
- -Certificate of Insurance effective 08/01/2010 and terminates 08/01/2011.
- -Reclamation agreement is dated October 14, 2003 and signed by both parties.
- -Storm Water Permit UTR000604, effective 01/01/07 and expires @ midnight 12/31/11 (under general permit UTR000000).

2. Signs and Markers

The mine ID signs are located at the contact points of the public road to the permit area and contains all of the appropriate information. All other signs and markers observed during the inspection were in compliance with the approved MRP.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Second quarter 2010 sediment pond inspections were done on June 25, 2010.

4.e Hydrologic Balance: Effluent Limitations

The July 2010 discharge monitoring reports were reviewed during the inspection. No discharges occurred from any of the outfalls.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile was inspected in the second quarter of 2010 on June 25, 2010. The pile appeared stable. No visible hazards were observed. The pile is being actively mined.

20. Air Quality Permit

The air quality permit DAQE-239-02 was issued on April 1, 2002 and remains in effect.

21. Bonding and Insurance

The bond is a collateral bond in the amount of \$1,375,737.31, as of December 31, 2006.